RCC: 1G

Ship: Y	'RBM 53 RMC 22	2807	J.O.: N322	5319F0033	Work Sp	ec#: 512-11-001	
COAR:	: 28	SSP: HRMC-HM&E-	19-0009	Contractor:	REGAL (CONFLUE	NCE CORP.)	
Author	ity: Not Authorize	d		I			
Contra	ctor Gap:	Governm	ent Gap: G9				
Reports	s: E-REGL-0005						
			0				
Modifica	ation of Specificatio	n Item: Exaust ∀ent Far	n F-4 Bracket,	Resilient Moun	s; repair and replace		
The follo	owing changes and	or additions apply to the	e work require	ments of the ori	ginal specification:		
3.3	Repair deteriorated brackets and damper linkage for Exhaust Vent Fan identified in 1.3.1, using 2.3 for guidance.						
3.3.1	Accomplish the requirements of 009-12 of 2.1, including Table 3, Column A, Lines One through 7, for exhaust vent fan bracket repairs.						
3.4	Replace with new resilient mounts for Exhaust Vent Fan identified in 1.3.1, using 2.3 for guidance.						
4.1	RCC linked to CFR 005.						(N
			For F	Pricing Onl	y		
	Price						
01	t 0't			Page 1 of 1	(b) (6)		May-19
Contrac	tor Signature	Date	-	aye i Ui i	Author	Prir	nted Date